

BRAND STATUS UPDATE

Helge Rottmann

On behalf of the BRAND team:

Gino Tuccari, Michael Wunderlich, Sven
Dornbusch, Armin Felke




BRAND PROJECT



- ▶ BRAND was part of EC-funded Joint Research Activity (JRA)
- ▶ Formally ended end of 2020
- ▶ Goal: build broad band receiver prototype for Effelsberg
 - ▶ 1.5 -15.5 GHz
 - ▶ Direct sampling; no down-conversion
- ▶ Status:
 - ▶ Finished: analogue components, feed, digital backend
 - ▶ Delayed: finalization of digital frontend
 - ▶ Pending: construction of shielding box (depends on digital frontend)

BRAND DIGITAL FRONTEND



BRAND_C (PCB 3rd revision)

- 30x40 cm
- 22 layers

IF Inputs (2 options):

- 2 x 28 GHz
- 4 x 14 GHz

Outputs:

- 64 x 10 Gbit

FPGAs:

- 4 x Xilinx Kintex UltraScale


Sampler:

- 112 Gbps @8bit

Power supply

- Max. 100A @ 0.95V (FPGA)

BRAND DIGITAL FRONTEND - SAMPLER



Sampler:

Total sample rate **112 Gsps** @8bit on a single chip (2 options)


- 2 x 56 Gsps
- 4 x 28 Gsps

Effective bits: **6.5**

Output: via **96** high-speed parallel lanes

Assembly of the the 96 output lines into a valid, fully-sampled data stream by 4 on-board FPGAs.

Zero-baseline fringe over the full band 0-28 GHz




BRAND ISSUES - PCB



Production of PCB board by Chinese manufacturer

- Challenging due to large size, large number of layers, high-currents
- Production of 6 boards: 1 x functional, 1 x minor defects (fixed), 4 x defective




Etching issue (missing lane)

BRAND ISSUES - PCB




Soldering issues found (could be fixed in-house):



Underheating in some areas of the PCB


Overheating in some areas of the PCB



BRAND ISSUES - PCB



Soldering issues due to uneven solder mask (fixed in-house):




Tilted power-regulators due to uneven solder mask surface

BRAND ISSUES – POWER SUPPLY



PCB power requirements:

	current	voltage
FPGA	Max. 100A	0.95V
Sampler	Max. 16A	1.25V
High-speed data lanes	Max. 12A	1V



Required voltage stability: < 10mV peak to peak

Not met by original design!


Issues:

- Sampler reset
- FPGA programming lost


BRAND ISSUES – POWER SUPPLY




Redesign of PCB power supplies



Original power supply



Reworked power supply



Stable operations of sampler and FPGA after fix

BRAND ISSUES: SYNCHRONISATION



Issue: Data arriving on the data lanes from the sampler to the FPGA was recognized as „invalid“ by the FPGA transceivers.

Issue very difficult to diagnose without the proper equipment.
Since July 2021: 40 GHz sampling scope

- Considerable progress in understanding the problem (eye pattern)
- Error in the PLL synchronization of the sampler threads

Code is fixed and “valid” data arrives at the FPGA transceivers over all 96 lanes.

BRAND STATUS & OUTLOOK



Next immediate steps:

- **Finalisation of BRAND FPGA firmware:**
 - Channelisation into 3.5 GHz sub-bands
 - VDIF packetizer
- **Finalisation of DBBC3 firmware:**
 - Bi-directional operation of Core3H transceivers
- **Zero-baseline fringe verification** of recorded VDIF data
 - DBBC3 with two digital input streams from the BRAND digital frontend


Milestone (end of march):

- Simplified Zero-baseline test between BRAND and DBBC3

MILESTONE ZERO-BASELINE TEST



Simplified zero-baseline test planned before end of March



BRAND SAMPLER ORDER



Delivery of sampler chips declined by manufacturer in 2021

- Minimum order quantity: 30 units
- EVN orders (via MPIfR): 11 units

Update:

- Money for ordering additional sampler chips secured within the DBBC4 project (MPG)
- Place order after successful lab tests
- MPIfR will contact partners again in spring/summer 2022